


Enhancement Concept Diagram Lower Willow Creek (Reach 7): **Alternative A**



Waterway Assessment Results

	Physical Condition	Water Quality	Natural Resources	Restoration	Total Points
Highest Possible Score	40	40	50	50	180
Existing Score	5	5	31	22	63
Projected Score*	32	32	44	22	130

*Projected score is based on successful implementation of the enhancement proposal in the alternative shown.



0 200 400 Feet
Scale

Draft: June 2006
Prepared by: LDCG
Aerial Photos: March 2004

Legend

- Existing Waterways
- Tax Lot Lines
- Land in Public or The Nature Conservancy Ownership
- Proposed Enhancements**
- Waterway Restoration/Re-alignment
- Existing Channelized Waterway to be Abandoned
- Trail Connection from Kluge to Farm Ridge Path (conceptual)



Lower Willow Creek looking north from 18th Avenue (following storm event)

